

WC 03018

Gearbox exchange E 1,5sl



Stand 030509ks>030806ks
P:\KS\PROJ\SP\9611 Windwin_AlleWin_WiCo\2003\wc03018gb_gearbox exch e1,5sl.doc
Wipro 0510



**At Enertrag AG
and Windwin KG in
Nechlin -
Uckermark /
Klockow Z1 during
030508**

*Out – down...each
change costs total ca
180– 200 000.- Euro !*



*Scenario east of
Village Nechlin
among more GE
1,5sl and new
Enercon E 66*



Sitz der Gesellschaft:

windwin GmbH & Co. KG

Gutenbergstr. 4 - 72631 Aichtal/GERMANY

Email: stk@windwin.de

Web: <http://www.windwin.de>

Geschäftsführer:

Dipl.-Ing. Karl Schlecht

Tel.: +0049-(0) 7127 599-302

Fax: +0049-(0) 7127 599-404

Mobil: +0049-(0)172-7123456

Bankverbindungen:

Dresdner Bank AG, Stuttgart

BLZ: 600 800 00, Kto.-Nr.: 33 040 24 00

LBBW BLZ: 600 501 01

Kto.Nr.: 2672 649

Amtsgericht Nürtingen

HRA-Nr. 2304

The New Gearbox from Lohmann&Stolterfoht waiting to be installed



Meanwhile until the end of July 2003 totally 5 gearboxes have been exchanged and probably more will follow. All are damaged with serious pittings on the inner ring of the planetary roller bearing as shown on website (expert's report in German)

<http://www.windwin.de/de/unternehmen/publikationen.asp> .

...the old one from Eickhoff coming down

GE installed in our Windturbine Z ! a Gearbox from Lohmann&Stolterfoht – not Flender as here in Nechlin.



Blades in perfect order with metallic flash catcher undamaged >>>